Last Update: 27 June 2007



1. PRODUCT AND COMPANY INDENTIFICATION

Company 24 Hour Emergency Response Information

Product Name: SBR / Neoprene Adhesive 1-800-364-3577 or (651)737-6501

Manufacturer: Southern Metal & Plastic Products Address: 3400 Treecourt Industrial Blvd

St. Louis MO 63122

Issues date: 05/02/2005 Supercedes Date: 06/08/2003

Product Use:

Specific Use: CONTACT ADHESIVE

2. COMPOSITION/INFORMATION ON INGREDIENTS

CAS Number	Content(% by Wt)	Chemical Name
64741-84-0	15-25	NAPHTHA SOLVENT LIGHT
9010-98-4	10-20	POLYCHLOROPRENE
110-54-3	10-20	N-HEXANE
67-64-1	10-20	ACETONE
78-93-3	7-13	METHYL ETHYL KETONE
68611-24-5	7-13	MAGNESIUM RESINATE
Mixture	5-10	MIXED HEXANE ISOMERS
108-88-3	3-7	TOLUENE
Mixture	1-3	MIXED HEPTANES

3. HAZARDS IDENTIFICATION

Emergency Overview

Odor, Color, Grade: grey/green, strong petroleum odor.

General Physical Form: Liquid

Immediate health, physical, and environmental hazards: Closed containers exposed to heat from fire may build pressure and explode. Extremely flammable liquid and vapor. Vapors may travel long distances along the ground or floor to an ignition source and flash back. May cause target organ effects. Contains a chemicals which can cause birth defects or other reproductive harm.

Potential Health Effects

Eye Contact:

MATERIAL SAFETY DATA SHEET PRODUCT or CHEMICAL NAME

Last Update: 27 June 2007



Moderate Eye Irritation: Signs/symptoms may include redness, swelling, pain, tearing, and blurred or hazy vision.

Skin Contact:

Moderate Skin Irritation: Signs/symptoms may include localized redness, swelling, itching, and dryness.

May be absorbed following inhalation and cause target organ effects.

Inhalation:

Gastrointestinal Irritation: Signs/symptoms may include abdominal pain, nausea, diarrhea and vomiting.

May be absorbed following ingestion and cause target organ effects.

Target Organ Effects:

Central Nervous system (CNS) Depression: Signs/symptoms may include headache, dizziness, drowsiness, incoordination, nausea, slowed reaction time, slurred speech, giddiness, and unconsciousness.

Prolonged or repeated exposure may cause:

Liver Effects: Signs/symptoms may include loss of appetite, weight loss, fatigue, weakness, abdominal tenderness and jaundice.

Central Neuropathy: Signs/symptoms may include irritability, memory impairment, personality changes, sleep disorder, and decreased ability to concentrate.

Peripheral Neuropathy: Signs/symptoms may include tingling or numbness of the extremities, incoordination, weakness of the hands and feet, tremors and muscle atrophy.

Kidney Effects: Signs/symptoms may include reduced or absent urine production, increased serum creatinine, lower back pain, increased protein in urine, and increased blood urea nitrogen (BUN).

Methyl ethyl ketone has been shown to potentiate the neurotoxic effects of n-hexane. Contains a chemical or chemicals which can cause birth defects or other reproductive harm.

4. FIRST AID MEASURES

The following first aid recommendations are based on an assumption that appropriate personal and industrial hygiene practices are followed.

If inhaled:

Remove person to fresh air. If signs/symptoms develop, get medical attention.

If on skin:

Remove contaminated clothing and shoes. Immediately flush skin with large amounts of water. Get medical attention. Wash contaminated clothing and clean shoes before reuse.

Southern Metal & Plastic Products
MATERIAL SAFETY DATA SHEET
PRODUCT or CHEMICAL NAME

Last Update: 27 June 2007



If in eyes:

Flush eyes with large amounts of water. If signs/symptoms persist, get medical attention.

If swallowed:

Do not induce vomiting. Give victim two glasses of water. Never give anything by mouth to an unconscious person. Get immediate medical attention.

5. FIRE FIGHTING MEASURES

Flammable Properties:

Autoignition temperature: No Data Available

Flash Point: -14 °F (Test Method: Tagliabue Closed Cup)

Flammable Limits- LEL 1% volume Flammable Limits- UEL 12.8% volume

Suitable extinguishable media:

Use fire extinguishers with class B extinguishing agents (e.g., dry chemical, carbon dioxide).

Hazards during fire fighting:

Not applicable. Closed containers exposed to heat from fire may build pressure and explode. Extremely flammable liquid and vapor. Vapors may travel long distances along the ground or floor to an ignition source and flash back.

Special Fire Fighting Procedures:

Water may not effectively extinguish fire; however, it should be used to keep fire-exposed containers and surfaces cool and prevent explosive rupture. Wear full protective equipment (Bunker Gear) and a self-contained breathing apparatus (SCBA).

Note: See STABILITY AND REACTIVITY (SECTION 10) for hazardous combustion and thermal decomposition information.

6. ACCIDENTAL RELEASE MEASURES

Refer to other sections of this MSDS for information regarding physical and health hazards, respiratory protection, ventilation, and personal protective equipment. Call 3M-HELPS line (1-800-364-3577) for more information on handling and managing the spill. Evacuate unprotected and untrained personnel from hazard area. The spill should be cleaned up by qualified personnel. Remove all ignition sources such as flames, smoking materials, and electrical spark sources. Use only non-sparking tools. Ventilate the area with fresh air. For large spill, or spills in confined spaces, provide mechanical ventilation to disperse or exhaust vapors, in accordance with good industrial hygiene practice. Warning! A motor could be an ignition source and could cause flammable gases or vapors in the spill area to burn or explode. Contain spill. For larger spills, cover drains and build dikes to prevent entry into sewer systems or bodies of water. Avoid contact with incompatible materials listed in the Reactivity Data Section. Cover spill area with a fire- extinguisher foam. An aqueous film forming foam (AFFF) is recommended. Working from around the edges of the spill inward, cover with bentonite, vermiculite, or commercially available inorganic absorbent material. Mix in sufficient absorbent until it appears dry. Remember, adding an absorbent material does not remove a toxic, corrosivity or flammability hazard. Collect as much of the spilled material as possible using non-sparking tools. Clean up residue with an appropriate solvent selected by a qualified and authorized person. Ventilate the area with fresh air. Read and following safety precautions on the solvent label and MSDS. Place in a metal container

Last Update: 27 June 2007



approved for transportation by appropriate authorities. Seal the container. Dispose of collected material as soon as possible.

In the event of a release of this material, the user should determine if the release qualifies as reportable according to local, state, and federal regulations.

7. HANDLING AND STORAGE

Handling

Ground containers securely when transferring contents. Wear low static or properly grounded shoes. Vapors may ignite explosively. May cause flash fire. Prevent build- up of vapors – open all windows and doors. Maintain vapor concentrations below recommended exposure limits. Use only with cross – ventilation. Without adequate ventilation, vapors may settle in low- lying areas. Keep away from heat, sparks, and open flame. Do not smoke or ignite matches, lighters, etc. Extinguish pilot lights and turn off stoves, ovens and other gas and electric appliances (space and water heaters, furnaces, etc.), electric motors, and other sources of ignition during adhesive use and until all vapors are gone; i.e., until the odor of vapors at the floor level has disappeared. Do not use electric light switches. Do not generate static sparks (such as by walking on carpet, etc.). Use the same precautions to any other container to which this product may by transferred. Avoid prolonged breathing of vapors. Avoid eye and skin contact. Keep container closed when not in use. If work area conditions prevent compliance with any of the above precautions, do not use the product. Keep out of the reach of children. For industrial or professional use only: Not intended for consumer sale or use. Follow OTHER PRECAUTIONARY INFORMATION below.

Storage

General Advice:

Store away from acids. Store away from heat. Store out of direct sunlight. Keep container in well-ventilated area. Keep container tightly closed. Store away from oxidizing agents.

8. EXPOSURE CONTROLS / PERSONAL PROTECTION

Advice on system design

Use with appropriate local exhaust ventilation. Provide appropriate local exhaust ventilation on open containers. Use general dilution ventilation and/or local exhaust ventilation to control airborne exposures to below Occupational Exposure Limits and/or control mist, vapor, or spray. If ventilation is not adequate, use respiratory protection equipment.

Personal Protective Equipment

Respiratory protection:

Avoid breathing of vapors, mists or spray.

Select one of the following NIOSH approved respirators based on airborne concentration of contaminants and in accordance with OSHA regulations: Half facepiece air- purifying respiratory with organic vapor/ acid cartridges and P95 particulate prefilters, Half facepiece air- purifying respirator with organic vapor/acid gad cartridges and N95 particulate prefilters, Half facepiece air- purifying respiratory with organic vapor/acid gas cartridges. Consult the current 3M Respiratory Selection Guide for additional information or call 1-800-243-46-30 for 3M technical assistance.

Skin protection:

Avoid skin contact.



Select and use gloves and/or protective clothing to prevent skin contact based on the results of an exposure assessment. Consult with your glove and/or protective clothing manufacturer for selection of appropriate compatible materials.

Gloves made from the following material(s) are recommended: Polyethylene/Ethylene Vinyl Alcohol.

Eye/Face protection:

Avoid eye contact. Avoid eye contact with vapors, mists, or spray.

The following eye protection(s) are recommended: Safety Glasses with side shields, Indirect Vented Goggles.

Prevention of Swallowing:

Do not eat, drink or smoke when using this product. Wash exposed areas thoroughly with soap and water.

EXPOSURE GUIDELINES

<u>Ingredient</u>	<u>Authority</u>	Type	<u>Limit</u>	Additional Information
ACETONE	ACGIH	TWA	500ppm	Table A4
ACETONE	ACGIH	STEL	750ppm	Table A4
ACETONE	OSHA	TWA, Vacated	750ppm	
ACETONE	OSHA	TWA	1000ppm	Tabel Z- 1
ACETONE	OSHA	STEL, Vacated	1000ppm	
N-HEXANE	ACGIH	TWA	50ppm	Skin Notation*
N-HEXANE	OSHA	TWA, Vacated	50ppm	Table Z-1A
N-HEXANE	OSHA	TWA	500ppm	Table Z-1A
METHYL ETHYL KETONE	ACGIH	TWA	200ppm	
METHYL ETHYL KETONE	ACGIH	STEL	300ppm	
METHYL ETHYL KETONE	OSHA	TWA	200ppm	Table Z-1A
METHYL ETHYL KETONE	OSHA	STEL	300ppm	Table Z-1
TOLUENE	ACGIH	TWA	50ppm	Skin Notation*;TableA4
TOLUENE	CMRG	STEL	75ppm	Skin Notation*
TOLUENE	OSHA	TWA, Vacated	100ppm	
TOLUENE	OSHA	STEL, Vacated	150ppm	
TOLUENE	OSHA	TWA	200ppm	Table Z-2
TOLUENE	OSHA	CEIL	300ppm	Table Z-2

^{*}Substance(s) refer to the potential contribution to the overall exposure by the cutaneous route including mucous membrane and eye, either by airborne or, more particularly, by direct contact with the substances. Vehicles can alter skin absorption.

VAC Vacated PEL: Vacated Permissible Exposure Limits [PEL] are enforced as the OSHA PEL in some states. Check with your local regulatory agency.

Source of Exposure Limit Data:

ACGIH: American Conference of Governmental Industrial Hygienists

CMRG: Chemical Manufacturer Recommended Guideline OSHA: Occupational Safety and Health Administration

AIHA: American Industrial Hygiene Association Workplace Environmental

Exposure Level (WEEL).

Southern Metal & Plastic Products MATERIAL SAFETY DATA SHEET PRODUCT or CHEMICAL NAME

Last Update: 27 June 2007



Form: Liquid

Odor: Strong petroleum
Color: grey/green
Autoignition temperature: No Data Available

Flash Point: -14°F [Test Method: Tagliabue Closed Cup]

Flammable Limits-LEL 1% volume Flammable Limits-UEL 12.8% volume

Boiling Point 132°F [Details: CONDITIONS: acetone]

Vapor Density: 3 [Ref Std: AIR=1]

Vapor Pressure: 180 mmHg [Details: CONDITIONS:@68°F]

Specific Gravity: .84 [Ref Std: WATER=1] PH: No Data Available

Melting Point: No Data Available

10. STABILITY AND REACTIVITY

Stability:

Stable

Materials and Conditions to avoid:

Strong oxidizing agents

Hazardous Polymerization:

Hazardous polymerization will not occur.

Hazardous Decomposition or By-Products:

SubstanceConditionAldehydesDuring CombustionHydrocarbonsDuring CombustionCarbon monoxideDuring CombustionCarbon dioxideDuring CombustionHydrogen ChlorideDuring CombustionKetonesDuring Combustion

11. TOXICOLOGICAL INFORMATION

Please contact the address listed on the first page of the MSDS for Toxicological Information on this material and/or its components.

12. ECOLOGICAL INFORMATION

ECOTOXICOLOGICAL INFORMATION

Not determined

MATERIAL SAFETY DATA SHEET PRODUCT or CHEMICAL NAME

Last Update: 27 June 2007



CHEMICAL FATE INFORMATION

Not determined

13. DISPOSAL CONSIDERATIONS

Waste disposal of substance:

Dispose of completely cured (or polymerized) wastes in a sanitary landfill. Incinerate uncured product in a permitted hazardous waste incinerator. As a disposal alternative, dispose of waste product in a permitted hazardous waste facility. Combustion products will include HCl. Facility must be capable of handling halogenated materials.

EPA Hazardous Waste Number (RCRA):

D001 (Ignitable), D035 (Methyl ethyl ketone)

Since regulations vary, consult applicable regulations or authorities before disposal.

14. TRANSPORT INFORMATION

ID Number(s):

62-1357-2630-5, 62-1357-2631-3, 62-1357-5530-4, 62-1357-5535-3, 62-1357-6530-3, 62-1357-7530-2, 62-1357-8530-1, 62-1357-8540-0, 62-1357-9531-8, 62-1357-9532-6, 78-8990-0393-9

Please contact the emergency numbers listed on the first page of the MSDS for Transportation Information for this material.

15. REGULATORY INFORMATION

Federal Regulations

Contact 3M for more information.

SARA hazard categories (EPCRA 311/312):

Fire Hazard-Yes Pressure Hazard-No Reactivity Hazard-No Immediate-Yes Delayed Hazard-Yes

Section 313 Toxic Chemicals subject to the reporting requirements of that section and 40 CFR part 72 (EPCRA):

Ingredient	C.A.S. No	% by Wt
TOLUENE	108-88-3	3-7
N-HEXANE	110-54-3	10-20
METHYL ETHYL KETONE	78-93-3	7-13

This material contains a chemical which requires export notification under TSCA Section 12[b]:

<u>Ingredient (Category if applicable)</u>	<u>C.A.S. No</u>	<u>Regulation</u>	<u>Status</u>
N-HEXANE	110-54-3	Toxic Substances Control Act	Applicable
		(TSCA) 4 Test Rule Chemicals	

Southern Metal & Plastic Products MATERIAL SAFETY DATA SHEET PRODUCT or CHEMICAL NAME

Last Update: 27 June 2007



ACETONE 67-64-1

Toxic Substances Control Act Applicable (TSCA) 4 Test Rule Chemicals

State Regulations

Contact 3M for more information.

CALIFORNIA PROPOSITION 65

IngredientC.A.S. NoClassificationTOLUENE108-88-3*Developmental Toxin

CHEMICAL INVENTORIES

The components of this product are in compliance with the chemical notification requirements of TSCA.

All applicable chemical ingredients in this material are listed on the European Inventory of Existing Chemical Substances (EINECS), or are exempt polymers whose monomers are listed on EINECS.

Contact 3M for more information.

INTERNATIONAL REGULATIONS

Contact 3M for more information

This MSDS has been prepared to meet the U.S. OSHA Hazard Communication Standard, 29CFR 1910.1200.

16. OTHER INFORMATION

NFPA Hazard Classification

Health: 2 Flammability: 3 Reactivity: 0 Physical Hazard: None

National Fire Protection Association (NFPA) hazard ratings are designed for use by emergency response personnel to address the hazards that are presented by short- term, acute exposure to a material under conditions of fire, spill, or similar emergencies. Hazard ratings are primarily based on the inherent physical and toxic properties of the material but also include the toxic properties of combustion or decomposition products that are known to be generated in significant quantities.

Revision Changes:

Section 16: NFPA hazard classification heading was modified.

Section 3: Other potential health effects heading was modified.

Copyright was modified

Section 8: Exposure guidelines data source legend was modified.

Section 3: Immediate physical hazard(s) was modified.

Section 5: Fire fighting procedures information was modified.

^{*}Warning: contains a chemical or chemicals which can cause birth defects or other reproductive harm.

Southern Metal & Plastic Products

MATERIAL SAFETY DATA SHEET PRODUCT or CHEMICAL NAME

Last Update: 27 June 2007



- Section 5: Unusual fire and explosion hazard information was modified.
- Section 7: Handling information was modified.
- Section 7: storage information was modified.
- Section 8: Eye/face protection phrase was modified.
- Section 15: 311/312 hazard categories heading was modified.
- Section 15: International regulations information was modified.
- Section 15: State regulations information was modified.
- Section 15: US federal regulations information was modified.
- Section 10: Hazardous polymerization heading was modified,
- Section 15: TSCA section 12[b] text was modified.
- Section 3: Other health effects information was modified.
- Section 16: NFPA explanation was modified.
- Section 15: Inventories information was modified.
- Section 15: EPCRA 313 text was modified.
- Section 15: California proposition 65 heading was modified.
- Section 15: California proposition 65 reproductive harm warning was modified.
- Section 12: Ecotoxicological information heading was modified.
- Section 12: Chemical fate information heading was modified.
- Section 8: Exposure guidelines legend was modified.
- Section 8: Exposure guidelines note was modified.
- Section 16: NFPA hazard classification for special hazards was modified.
- Section 3: Other health effects information (reproductive hazards) was modified.
- Section 3: Other potential health effects was modified.
- Section 12 Ecotoxicological phrase was modified.
- Section 2: Ingredient phrase was added.

DISCLAIMER:

The information in this Material Safety Data Sheet (MSDS) is believed to be correct as of the date issued. 3M MAKES NO WARRNATIES, EXPRESSED OR IMPLIED, INCLIDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCGANTABILITY OR FITNEDD FOR A PARTICULAR PURPOSE OR COURSE OF PERFORMANCE OR USAGE OF TRADE. User is responsible for determining whether the 3M product is fit for a particular purpose and suitable for user's method of use or application. Given the variety of factors that can effect the use and application of a 3M product, some of which are uniquely within the user's knowledge and control, it is essential that the user evaluate the 3M product to determine whether it is fit for a particular purpose and suitable for user's method of use or application.

3M provides information in electronic form as a service to its costumers. Due to the remote possibility that electronic transfer may have resulted in errors, omissions or alterations in this information, 3M makes no representatives as to its completeness or accuracy. In addition, information obtained from a database may not be as current as the information in the MSDS available directly from 3M.

3M MSDSs are available at www.3M.com